

# Contents

<b>Preface</b> .....	<b>V</b>
<b>Acknowledgments</b> .....	<b>VII</b>
<b>The Author</b> .....	<b>IX</b>
<b>1 Introduction</b> .....	<b>1</b>
1.1 Benefits of Injection Molding .....	4
1.2 The Injection Mold .....	6
1.2.1 The Role of the Injection Mold .....	6
1.3 What Is an Injection Mold? .....	7
1.3.1 Elements of an Injection Mold .....	9
1.4 Classification of Molds .....	13
1.5 Continued Innovation in Molds and Hot Runners .....	14
1.6 The Injection Molding Machine .....	14
<b>2 Overview of Plastics for Mold Design</b> .....	<b>17</b>
2.1 What Is Plastic? .....	17
2.2 Plastics Terminology .....	18
2.3 Polymer Orientation .....	20
2.3.1 Shrinkage .....	20
2.3.2 Multiple Shrinkages .....	22
2.4 Additives .....	23
2.5 Mechanical Properties of Plastics .....	24
2.6 How Molten Plastics Behave .....	25
2.6.1 How Plastics Flow .....	25

2.6.1.1	Pseudo-Plastic Behavior . . . . .	26
2.6.2	Plastic Flow in Runners and Cavities . . . . .	28
2.7	Degradation . . . . .	30
2.8	Selection and Requirements for Plastic Materials . . . . .	31
<b>3</b>	<b>Plastic Part Design for Mold Designers . . . . .</b>	<b>33</b>
3.1	Plastic Part Drawing . . . . .	35
3.2	Product Shape: How Can the Product Best Be Molded? . . . . .	38
3.3	Parting Line (P/L) . . . . .	41
3.4	Uniform Wall Thickness . . . . .	43
3.5	<i>L/t</i> Ratio (Length of Flow Divided by Wall Thickness) . . . . .	46
3.6	Drafts . . . . .	47
3.7	Corners, Fillets, and Chamfers . . . . .	48
3.8	Ribs and Bosses . . . . .	49
3.9	Rim Designs . . . . .	51
3.10	Stripped Undercuts . . . . .	52
3.11	Sidewall Windows in the Part . . . . .	52
3.12	Gate Location and Number of Gates . . . . .	53
3.12.1	CAE Filling Analysis for Gate Location Optimization . . . . .	57
3.12.2	Two or More Gates per Cavity – Large Products . . . . .	59
3.12.3	Gate Dimple . . . . .	61
3.12.4	Recessed Gate . . . . .	61
3.12.5	Deep Undercuts and Mold Design Complexity . . . . .	62
3.13	Re-Design of the Product to Avoid the Need for Side Cores . . . . .	63
3.13.1	Selecting Other than the Conventional Parting Line . . . . .	63
3.14	Shape of Threads and Undercuts . . . . .	64
3.15	Need for Multi-Stage Ejection . . . . .	67
3.16	Post-Molding Operations versus Mold Complexity . . . . .	69
3.17	Plastic Part Tolerances and Effect on Mold Design . . . . .	70
3.17.1	General and Specific Plastic Part Tolerances . . . . .	72
3.17.2	Are Special Fits with Matching Products Required? . . . . .	73
3.17.3	Tolerances for the Filling Volume . . . . .	73
3.18	Stacking of Products and Free Dispensing . . . . .	74

3.19	Deliberate Mismatches for Easy Mold Design	78
3.19.1	Mismatch at the Parting Line	78
3.19.2	Mismatch between Two Matching Pieces, such as Box and Lid	80
3.20	Surface Finish	81
3.20.1	Finish of Molding Surfaces	82
3.20.1.1	Molding Surface Finish for Ease of Ejection	84
3.20.2	Texturing of Surfaces	85
3.21	Fitting Surfaces of Mold Parts	86
3.22	Engravings	86
3.22.1	Engravings versus Applied Labels	86
3.22.2	Two-Color and Two-Material Engraving	87
3.22.3	Depth of Engravings	89
3.22.4	Font Style and Size of Artwork	90
3.22.5	Polarity of Engraving	91
3.22.6	Are the Locations Selected for Engraving Practical?	91
3.22.7	Engravings in the Walls and Bottoms of Products	92
3.22.7.1	Engravings on the Outside of the Product (Engraved Cavities)	92
3.22.7.2	Engravings on the Inside of the Product (Engraved Cores)	94
3.23	General Appearance of the Product	95
3.23.1	Flatness	95
3.23.2	Sinks and Voids	99
3.23.3	Witness Lines	101
3.23.3.1	Parting Line Flash	102
3.23.3.2	Gaps between Cavity and/or Core Parts and Inserts	102
3.23.3.3	Clearance of Ejector Pins and Ejector Sleeves	104
3.23.3.4	Hiding the Gate Mark	105
3.23.4	Weld Lines	105
3.23.4.1	Location of Weld Lines	106
3.23.5	Surface Defects (Flow Marks, Splay, Record Grooves, Haze, Jetting, Hooks, and Ripples)	107

3.24	Identification of the Molded Piece .....	109
3.25	Product Strength Requirements .....	110
3.25.1	The Role of Gate Location in Increasing Product Strength ...	111
3.26	Special Features .....	112
3.26.1	Holes and Counter-Bores for Assembly Screws or Rivets .....	113
3.26.2	Hinges and Snaps .....	114
<b>4</b>	<b>Specifying the Right Machine for the Mold .....</b>	<b>117</b>
4.1	Required Clamp Size (Tonnage) .....	120
4.2	Required Opening Stroke and Shut-Height .....	125
4.3	Platen Mounting Pattern and Ejector Positions .....	127
4.4	Locating Ring Size and Machine Nozzle Size .....	127
4.5	Extruder Sizing and Specification .....	127
4.5.1	Extruder Shot Size Calculation .....	128
4.5.1.1	Shot Size Calculation for Cold Runners .....	129
4.5.1.2	Shot Size Calculation for Hot Runners .....	131
4.5.1.3	Extruder Sizing Calculation .....	131
4.5.2	Requirements for Machine Plasticizing Capacity .....	132
4.5.2.1	Impact of Light-Weighting the Product .....	135
4.5.3	Screw Selection .....	136
4.6	Machine Nozzle Selection .....	136
4.6.1	Open Nozzles .....	137
4.6.2	Shut-off Nozzles .....	139
4.7	Injection Unit Selection .....	143
4.7.1	Reciprocating Screw versus Two-Stage Injection Units .....	143
4.7.2	Injection Speed and Pressure Requirements .....	145
4.7.2.1	Need for High Injection Pressures .....	149
<b>5</b>	<b>Factors Affecting the Design of an Injection Mold .....</b>	<b>151</b>
5.1	Total Equipment Productivity (TEP) Objectives .....	151
5.2	Cycle Time .....	153
5.3	Projected Annual Requirements .....	153
5.4	Purpose of the Mold .....	154
5.4.1	Prototype Mold .....	155

5.4.2	Experimental Mold .....	156
5.4.3	Combination of Prototype and Experimental Mold .....	157
5.4.4	Production Mold .....	158
5.4.5	New Products .....	158
5.4.6	Existing Product, Large Quantities .....	159
5.4.7	Limited Quantities, Limited Product Lifecycle .....	160
5.4.8	Short Runs, Small Production Requirements .....	160
5.5	The Injection Molding Machine .....	161
5.6	The Plant Environment .....	162
5.6.1	Condition of Ambient (Shop) Air .....	163
5.7	Coolant Supply .....	165
5.7.1	Is the Cooling Water Clean? .....	166
5.7.2	Chiller Sizing Guidelines .....	167
5.8	Power Supply .....	168
<b>6</b>	<b>Cycle Time Estimation .....</b>	<b>171</b>
6.1	Factors Impacting Cycle Time .....	172
6.1.1	Type of Plastic .....	172
6.1.2	Wall Thickness of Product .....	174
6.1.3	Mold Materials .....	175
6.1.4	Efficiency of Cooling .....	176
6.1.4.1	Molds for Small-Scale Production (Fewer than Approx. 1000 Pieces) .....	177
6.1.4.2	Molds for Large-Scale Production of Products 0.4–1.3 mm (0.015–0.050") Thick .....	177
6.1.4.3	Molds for Large-Scale Production of Products >3 mm (0.120") Thick .....	178
6.1.4.4	Molds for Most Other Products .....	181
6.1.5	Venting .....	182
6.1.6	Ejection .....	182
6.1.7	Molding Machine .....	183
6.1.7.1	Machine Dry Cycle .....	183
6.1.7.2	Timing of Ejection and Stroke Required .....	186
6.1.8	Impact of Cold Runners versus Hot Runners on Cycle Time ..	195
6.2	Estimating Cycle Time .....	196

<b>7</b>	<b>Product Cost Estimation</b> .....	<b>201</b>
7.1	Machine Hour Cost per Unit Molded .....	201
7.2	Mold Cost per Unit Molded .....	204
7.3	Labor Costs .....	206
7.4	Estimating Product Cost .....	207
<b>8</b>	<b>Mold Layout, Drawings, and Inspection</b> .....	<b>217</b>
8.1	Steps to Designing the Mold .....	217
8.2	Information and Documentation .....	218
8.2.1	Machine Specifications .....	220
8.2.1.1	Mechanical Features .....	220
8.2.2	Productivity Features .....	223
8.2.3	Additional Requirements .....	224
8.3	Determining the Mold Cavitation .....	227
8.3.1	Minimum Number of Cavities .....	228
8.3.2	Preferred (Practical) Number of Cavities .....	230
8.4	Assembly and Detail Drawings .....	231
8.4.1	Drawings and Views .....	231
8.4.2	Arrangement of Views .....	232
8.4.3	Notes on Drawings .....	233
8.4.4	Additional Information on the Drawings .....	233
8.5	Mold Layout and Assembly Drawings .....	233
8.5.1	Machine Platen Layout .....	233
8.5.2	Symmetry of Layout, Balancing of Clamp .....	234
8.5.3	The Views .....	234
8.5.4	Completing the Assembly Drawing .....	234
8.5.5	Bill of Materials (BOM) and “Ballooning” .....	235
8.5.6	Finishing Touches .....	235
8.6	Inspection Features on Drawings .....	236
8.6.1	Rollers or Roller Balls .....	236
8.6.2	How to Inspect Tapers .....	237
8.6.2.1	External Tapers .....	237
8.6.2.2	Internal Tapers .....	237

8.6.2.3	Angled Surfaces .....	238
8.6.2.4	Construction (Checking) Balls .....	239
8.7	Chamfers and Radii .....	240
8.7.1	General Information .....	240
8.7.2	Specifying Chamfers .....	241
8.7.3	Radii in Corners .....	242
<b>9</b>	<b>Mold Shoe Design .....</b>	<b>243</b>
9.1	Mold Plates .....	245
9.2	Mold Hardware .....	247
9.3	Location of Fittings, Hoses, and Cables .....	248
9.4	Forces Affecting Mold Shoes .....	248
9.4.1	Deflection of Mold Plates .....	249
9.4.2	Calculation of Plate Deflection and Stress .....	250
9.5	Selection of Materials for Mold Plates .....	252
9.6	Guiding of Moving Plates .....	253
9.6.1	Gibs .....	253
9.6.1.1	Pillars and Bushings .....	254
9.6.1.2	Dowel Pins and Bushings .....	254
9.6.1.3	Leader Pins with Piston and Stroke Limiters .....	255
9.7	Mounting Holes and Clamp Slots .....	256
9.8	Locating Rings .....	257
9.9	Mold Handling – Lift Holes, Lift Bars, and Latches .....	257
9.9.1	Lift Bars .....	257
9.9.2	Latches .....	260
9.9.2.1	Latches for Mold Servicing .....	260
9.10	Mold Identification Nameplates .....	263
<b>10</b>	<b>Cavity and Core Design Overview .....</b>	<b>265</b>
10.1	Mold Cavity Space .....	265
10.2	Plastic versus Steel Part Drawing .....	266
10.3	The Preliminary Stack Layout .....	267
10.3.1	Where Should the Parting Line Be Located? .....	267
10.3.1.1	Primary Parting Line .....	268

10.3.1.2	Secondary Parting Lines: Split Molds and Side Cores .....	270
10.3.2	Will the Product Pull out of the Cavity and Stay on the Core? .....	271
10.3.3	Will the Product Eject Easily from the Core? .....	273
10.3.4	Is the Cavity Balanced? .....	275
10.4	Determining the Method of Cavity Construction .....	276
10.4.1	Cavity and/or Core Are Cut Right into the Mold Plate .....	277
10.4.2	Individual Cavities and Cores .....	277
10.5	Stack Sizing and Total Area of the Stack .....	278
10.6	Forces on the Cores and Cavities .....	279
10.6.1	Checking for Sufficient Steel Shut-off Area in Stack .....	280
10.6.2	Checking for Stack Compression due to Clamp Tonnage .....	281
10.6.3	Checking for Acceptable Hoop Stress in the Cavity .....	283
10.7	Core and Cavity Material Selection .....	285
10.8	Determining the Stack Construction .....	286
10.9	Venting .....	287
10.9.1	Parting Line (P/L) Venting .....	289
10.9.2	Vent Grooves and Channels .....	289
10.9.3	Vent Pins .....	290
10.9.4	Venting of Ribs .....	291
10.9.5	Venting the Bottom of a Cavity .....	291
10.9.6	Core Cap and Core Sidewall Venting .....	292
<b>11</b>	<b>Ejection .....</b>	<b>293</b>
11.1	Manual or Semi-Automatic Ejection .....	294
11.2	Automatic Ejection .....	295
11.3	Basic Requirements for Ejection .....	297
11.3.1	Machine Opening Stroke for Ejection .....	297
11.3.2	Venting for Ease of Ejection .....	300
11.3.3	Surface Finish Forces on Ejection .....	301
11.3.3.1	Mold Surface Roughness .....	301
11.3.3.2	Molding Surface Finish Guidelines for Ejection ...	302
11.4	Force Required for Ejection .....	303



11.5	Where to Eject the Product	303
11.5.1	Ejection of Deep Cup-Shaped Parts	305
11.5.2	Ejection of Parts with Deep Ribs	305
11.5.3	Ejection of Bosses	307
11.5.4	Ejection of Shallow Parts	308
11.5.5	Ejection of Rim Shapes	309
11.5.6	Ejection of Cold Runners	311
11.6	Ejector Pins, Blade Ejectors, and Sleeves	315
11.6.1	Ejector Pin Clearance (Fit) and Length of Land	317
11.6.2	Blade Ejectors	318
11.6.3	Number, Size, and Location of Ejector Pins	320
11.6.3.1	Ejector Pin Sizing	320
11.6.3.2	Ejector Pin Locations	321
11.6.4	Finish of Ejector Pins and Bores	322
11.6.5	Preventing Ejector Pins from Turning	323
11.7	Ejector and Ejector Retainer Plates	324
11.7.1	Ejection Forces	324
11.7.2	Injection Forces	325
11.7.3	Number and Location of Machine Ejectors to Be Used	325
11.7.4	Calculation of Ejector Plate Deflection	325
11.7.5	Ejector Pin Retainer Plate	326
11.7.6	Ejector Return Pins	328
11.7.7	Ejector Box	329
11.7.7.1	Guiding Ejector Plates	331
11.7.8	Returning the Ejector Plate	332
11.7.8.1	Tie Ejector Plate to Machine's Ejector Plate	333
11.7.8.2	Linkages Attached to the Mold	333
11.7.8.3	Return Springs	333
11.7.8.4	Air Cylinders (Air Springs) for Ejector Return	336
11.7.8.5	Early Ejector Return Systems	337
11.8	Stripper Ejection	338
11.8.1	General Rules for Stripper Ejection	339
11.8.2	Guiding the Stripper Plate	341

11.8.3	Stripper Rings .....	343
11.8.3.1	Fixed Stripper Rings or Stripper Inserts .....	343
11.8.3.2	Floating Stripper Rings .....	344
11.8.4	Stripper Bars .....	346
11.8.5	Stripper Ring Ejection of Lids .....	347
11.8.6	Stripping from the Injection (Cavity) Side .....	348
11.9	Air Ejection .....	348
11.9.1	Requirements and Timing for Air Ejection .....	350
11.9.2	Poppet Air Ejection .....	351
11.9.3	Core Air .....	355
11.9.3.1	Fixed Core Air .....	355
11.9.3.2	Stroking Core Air .....	357
11.9.3.3	Combination of Air Poppet and Stroking Core Air .....	358
11.9.4	Blow-off Jets .....	359
11.9.5	Blow-down Jets .....	360
11.9.6	Air Ejection from the Cavity Side .....	361
11.10	Ejection of Significant Undercuts .....	363
11.10.1	Cam Ejection (Internal and External) Using Neck Rings .....	363
11.10.2	Core Pull Ejection .....	365
11.10.3	Collapsible Cores .....	367
11.10.4	Lifter Ejection .....	369
11.10.5	Sliders .....	371
11.10.5.1	Split-Cavity Movement on Angled Pins .....	374
11.10.6	Unscrewing Ejection .....	375
11.10.7	Cam and Harmonic Linkage Ejection .....	376
11.11	Multiple Ejection Strokes .....	377
11.12	Multi-Stage Ejection .....	378
11.12.1	Why and When to Use Multi-Stage Ejection .....	378
11.12.2	Typical Two-Stage Ejection Actuations .....	379
11.12.2.1	Latch Locks (Internal and External) .....	381
11.12.2.2	Two-Stage Ejection with Levers .....	383
11.12.3	Moving-Cavity Ejection Assist .....	384

<b>12</b>	<b>Mold Cooling</b>	<b>387</b>
12.1	Injection and Mold Temperatures for Common Plastics	390
12.2	Coolant Requirements for a Mold	391
12.3	What Affects Mold Cooling Performance?	392
12.3.1	Temperature of the Cooling Medium	393
12.3.2	Achieving Steady-State Temperature in the Mold	393
12.4	Principles of Heat Transfer and Thermodynamics	395
12.4.1	Heat Transfer Basics	396
12.4.2	Melting and Cooling Behavior of Plastics	398
12.4.3	Conduction and Thermal Conductivity	399
12.4.3.1	Thermal Conductivity Values	400
12.4.4	Convective Heat Transfer	401
12.4.4.1	Reynolds Number (Re)	401
12.4.4.2	Pressure Drop of Coolant Supply and Return Lines	403
12.4.4.3	Cross-Section of Channels	403
12.4.4.4	Length of Cooling Lines	403
12.4.4.5	Coolant Viscosity	403
12.4.4.6	Condition of Channels	404
12.5	Calculation of Cooling Requirements for a Mold	404
12.5.1	Heat Input Required to Condition the Plastic for Injection	404
12.5.2	Cooling Required to Remove the Inputted Heat	405
12.5.3	Temperature of Cooling Water	406
12.5.4	Quantity of Cooling Water Required	407
12.5.5	Efficiency of Cooling on Required Water Flow	408
12.6	General Cooling Design Rules	409
12.7	Cooling Channels in Plates	411
12.7.1	Series and Parallel Plate Cooling	412
12.7.2	Distance of Waterlines from Holes and Surfaces	415
12.7.3	Plugging of Cooling Channels	416
12.7.4	Plugs and Baffles in Plates	417
12.7.5	Cooling of Hot Runner Plates	419
12.7.5.1	Calculation of the Sizes of Cooling Channels for Hot Runner Plates	420

12.8	Layout of Cooling Channels in Inserts .....	422
12.8.1	Shrinkage of Plastic and Cooling Layout .....	424
12.8.2	Preventing Water Leakage in the Mold .....	426
12.8.3	Cooling Channel Distances in Inserts .....	428
12.8.4	Distance to Pipe Threads and Fittings .....	430
12.8.5	Cooling Channels Split between Inserts .....	430
12.8.6	Design of Insert Cooling for Flat Products .....	431
12.8.6.1	Drilled and Milled Cooling Circuits in Flat Parts ..	431
12.8.7	Cooling Design for Cup-Shaped Products .....	433
12.8.7.1	Cavity Cooling in Cup-Shaped Products .....	433
12.8.7.2	Core Cooling of Cup-Shaped Products .....	439
12.8.7.3	Cooling of Inserts .....	448
12.8.8	Use of CAE Molding Simulation for Cooling Design and Warpage Analysis .....	449
12.9	Supplying Water to the Mold .....	452
12.10	Thermal Expansion .....	453
<b>13</b>	<b>Mold and Stack Alignment .....</b>	<b>455</b>
13.1	Leader Pin and Bushing Alignment .....	457
13.2	Taper or Straight Interlock Alignment between Plates .....	459
13.3	Taper Lock between Each Cavity and Core .....	462
13.3.1	Backing up a Taper .....	466
13.3.2	Core Lock and Cavity Lock Alignment .....	467
13.4	Preloads .....	470
13.4.1	Restoring Preload by Grinding of the Tapers .....	474
13.4.2	Preload Stresses .....	475
13.4.3	Mounting of Stacks to Mold Plates .....	475
13.5	Over-Constrained Alignment .....	476
<b>14</b>	<b>Melt Distribution and Gate Design .....</b>	<b>479</b>
14.1	Cold Runners .....	481
14.1.1	Cold Runner, Single-Cavity Molds .....	481
14.1.2	Cold Runner, Two-Plate Molds .....	481
14.1.3	Cold Runner, Three-Plate Molds .....	483

14.1.4	Cold Runner Gate Types and Configurations . . . . .	484
14.1.4.1	General Features of a Cold Runner Gate . . . . .	484
14.1.4.2	Edge, Fan, Tab, and Diaphragm Gates . . . . .	485
14.1.4.3	Tunnel Gates . . . . .	487
14.1.4.4	Multiple Tunnel Gating . . . . .	489
14.1.4.5	Curved or Submarine Tunnel Gating . . . . .	489
14.1.4.6	Three-Plate Gates . . . . .	490
14.1.4.7	Optimizing the Cold Runner Gate Placement . . . . .	491
14.1.5	Layout and Balancing of Cold Runner Melt Channels . . . . .	493
14.1.5.1	Multi-Cavity Runner Layouts (One Gate per Part) . . . . .	496
14.1.5.2	Single-Cavity Multi-Gate Runner Layouts . . . . .	499
14.1.6	Cold Runner Ejection . . . . .	499
14.2	Insulated Runners . . . . .	499
14.3	Hot Runners . . . . .	500
14.3.1	Considerations for Specifying a Hot Runner . . . . .	505
14.3.2	Overview of Hot Runner Design . . . . .	506
14.3.3	Layout and Balancing of Hot Runner Melt Channels . . . . .	507
14.3.3.1	Bridge and Sub-Manifolds . . . . .	513
14.3.4	Melt Channel Sizing . . . . .	514
14.3.4.1	Plastic Inventory in the Hot Runner . . . . .	515
14.3.5	The Hot Runner Manifold . . . . .	516
14.3.5.1	Locating the Manifold . . . . .	516
14.3.5.2	Thermal Expansion of the Manifold, Sealing the Hot Runner Systems, and Nozzle Tip Position . . . . .	517
14.3.5.3	Manifold Supports (Back-up Insulators) . . . . .	518
14.3.5.4	Manifold Plate and Manifold Backing Plate . . . . .	520
14.3.6	Heating of the Hot Runner . . . . .	522
14.3.6.1	Basics of Resistance Heaters . . . . .	523
14.3.6.2	Heaters . . . . .	523
14.3.6.3	Heat Input per Mass of the Hot Runner Manifold . . . . .	525
14.3.6.4	Thermocouples (T/Cs) . . . . .	526
14.3.7	Hot Runner Nozzles . . . . .	528

14.3.8	Nozzle Tips and Gating in Hot Runners .....	529
14.3.8.1	Hot-Tip Gates .....	530
14.3.8.2	Valve Gates .....	533
14.3.8.3	Slot Gating .....	537
14.3.9	Hot Runner Temperature Controls .....	538
14.3.10	Hot Runner Gate Location .....	539
14.3.11	Hot Runner Gate Sizing .....	539
14.3.11.1	Gate Sizing Methods .....	540
14.3.11.2	Gate and Melt Channel Size Calculation .....	541
14.3.11.3	Empirical Calculation of Gate Size .....	542
14.3.11.4	Gate Land Length .....	543
14.3.12	Gate Inserts (Gate Pads) .....	543
14.4	Hot and Cold Runner Molds in Combination .....	544
14.5	Selection of Hot Runner or Cold Runner System .....	546
<b>15</b>	<b>Selection of Mold Materials .....</b>	<b>549</b>
15.1	Forces on the Mold Affect Material Choices .....	550
15.1.1	Characteristics of Steels and Other Mold Materials .....	551
15.2	Steel Properties .....	554
15.2.1	Types of Steels .....	558
15.2.1.1	Pre-Hardened Steels .....	558
15.2.1.2	Tool Steels .....	558
15.2.1.3	Stainless Steels .....	559
15.2.1.4	Copper Alloys .....	559
15.3	Quality of Materials .....	559
15.4	Manufacturing Considerations for Choosing Materials .....	560
15.4.1	EDM .....	560
15.4.2	Welding .....	560
15.5	Heat Treatment .....	560
15.6	Overview of Surface Treatments .....	562
15.7	Hardness of Mating Parts .....	563

<b>16</b>	<b>Fasteners</b> .....	<b>565</b>
16.1	How Screws Work .....	567
16.2	Rolled versus Cut Threads .....	568
16.3	Holding Action and Preload of Screws .....	569
16.4	Influence of Temperature on Screws .....	573
16.5	Effect of Cyclical Loads on Screws .....	574
16.6	Screw Standards and Properties .....	574
16.7	Length of Thread Engagement .....	575
16.8	Additional Recommendations Regarding Screws .....	576
16.8.1	Always Use Standard Available Screw Sizes and Lengths ....	576
16.8.2	Increase the Depth of the Counter-Bore .....	577
16.9	Use of Set Screws .....	578
16.10	Holding Screws in Place (if Needed) .....	578
16.10.1	Lock Washers .....	578
16.10.2	Screw-Securing Compounds .....	579
16.10.3	Screws Secured by Plastic Inserts (Nylok™, etc.) .....	579
<b>17</b>	<b>Dimensioning and Tolerancing</b> .....	<b>581</b>
17.1	Conventional versus Geometric Tolerancing .....	583
17.2	Limitations of Conventional Dimensions and Tolerances .....	584
17.2.1	Origins of Measurement .....	585
17.2.2	Non-Repeatable Sizes and Centers .....	586
17.2.3	Orientation and Angles .....	587
17.2.4	Tolerance Accumulation .....	589
17.3	Geometric Dimensioning and Tolerancing .....	591
17.3.1	Three Core Steps for Applying or Inspecting GD&T .....	592
17.3.2	Geometric Tolerancing Benefits versus Conventional Tolerancing .....	593
17.3.2.1	Clear Setup and Origins of Measurement .....	593
17.3.2.2	Geometric Controls Apply to Features, not to Dimensions .....	595
17.3.2.3	Repeatable Sizes and Centers .....	597
17.3.2.4	Tolerance Accumulation Is Minimized .....	597
17.3.2.5	Tolerance Zones Are Uniform .....	598

17.3.2.6	Control of Patterns of Features	598
17.3.2.7	A Single Interpretation	598
17.4	Implementation of Geometric Tolerancing	598
17.4.1	Implementation of GD&T-Lite (not Recommended)	599
17.4.2	Implementation of GD&T Integration	599
17.4.3	Implementation of Model-Based Definition	600
17.5	Considerations for Tolerancing	601
17.5.1	CAD Modelling Practices	601
17.5.2	Materials, Manufacturing, and Inspection	602
17.5.3	Thermal Expansion and Tolerancing	603
17.6	Application of GD&T to Mold Components	603
17.6.1	GD&T Applied to an Injection Mold Core	604
17.6.2	GD&T Applied to an Injection Mold Lock Ring	606
17.6.3	GD&T Applied to an Injection Mold Core Plate	608
17.6.4	GD&T and Mold Engineering	611
<b>18</b>	<b>Mold Design References</b>	<b>613</b>
18.1	Plastic Housing (Using Shut-offs)	613
18.2	Facemask	615
18.3	Plastic Cutlery	618
18.4	Vial	621
18.5	Open-Ended Floss Spool Tube	623
18.6	Overcap Lid (Using Stripper Ring Ejection)	626
18.7	Plug Lid	628
18.8	Urine Tub Cap (Using Stripper Ring Ejection)	634
18.9	Deli or Yellow Fats Container (Using Air Ejection and with Cavity Lock Alignment)	637
18.10	Stadium Cup (Using Core Lock Alignment)	640
18.11	Polystyrene Tumbler (Using Stripper Ring Ejection)	643
18.12	False-Bottom Cup (Using Moving Cavity and Air Ejection)	648
18.13	Round Closure (Using Stripper Ring (Bump-off) Ejection)	649
18.14	Paint Pail with Handle Inserts	652
18.15	Rectangular Container with Tamper-Evident Skirt	654
18.16	Power Tool Housing	657



18.17 Rear Hatch Door .....	662
18.18 Crinkle Bag .....	663
18.19 Preform (Using Neck Ring Ejection) .....	665
18.20 Living Hinge Cap .....	670
18.21 Rectangular Box with Undercuts (Using Split-Cavity Mold) .....	673
18.22 Detergent Cap (Using Unscrewing Ejection) .....	674
18.23 Folding Crate .....	679
18.24 Automotive Panel Cover .....	682
18.25 Pallet .....	683
18.26 Automotive Covers .....	685
18.27 Double-Walled Threaded Cap (Using Collapsible-Core Mold) .....	687
18.28 Automotive Cover .....	689
18.29 Externally Threaded Cap Mold .....	690
18.30 Oxygen Mask (with Side Core Retraction) .....	692
18.31 Living-Hinge Case .....	694
18.32 Iron Housing (Using Split-Cavity Mold) .....	697
18.33 Oral Care Product (Using Split-Cavity Mold) .....	699
18.34 Actuator (Using Split Cavity with Multi-Stage Ejection) .....	705
<b>19 Mold Testing, Approval, and Troubleshooting .....</b>	<b>707</b>
19.1 Information to Be Supplied to the Mold Tester .....	707
19.2 Dry-Cycle Testing before Injecting Plastic .....	708
19.2.1 Bluing to Ensure Proper Shut-off, Venting, and Taper Fit .....	710
19.2.2 Procedure for Aligning Mold Halves in the Injection Molding Machine .....	712
19.2.3 Lead Test Procedure to Check Wall Thicknesses and Alignment .....	712
19.3 Initial Mold Start-up and First Shots .....	713
19.3.1 Mold Start-up Procedure .....	714
19.4 Changing Materials or Colors .....	718
19.4.1 General Color Change Procedure .....	719
19.5 Mold Test Information and Data to Be Collected .....	720
19.5.1 Core Shift Mapping .....	721

19.6	APQP and PPAP .....	722
19.7	Mold Test Troubleshooting Guide .....	723
<b>20</b>	<b>Appendix .....</b>	<b>733</b>
	Appendix 1: Mold Material Properties .....	733
	Appendix 2: Frequently Used Conversion Factors .....	735
	Appendix 3: Plastics and their Abbreviations .....	737
	Appendix 4: Mold Design Review Checklist .....	739
	Appendix 5: Contents of a Mold Manual .....	745
	Appendix 6: Mold Setup Guide Template .....	746
	Appendix 7: Order Confirmation Template .....	751
	Appendix 8: General Properties of Plastics .....	753
	Appendix 9: Thermal Properties of Plastics .....	755
	Appendix 10: Mechanical Properties of Plastics .....	757
	Appendix 11: Thermal and Processing Properties of Plastics .....	761
	Appendix 12: Mold Preventative Maintenance Checklist .....	766
	Appendix 13: Surface Finishes .....	767
	<b>Index .....</b>	<b>769</b>